

Project Information

Surveyor Name	BUENO_R	Certificate Number	P0043820-082023
Owner		Customer	RIVERBEND OF NAPLES MOBILE HOA
Drainage Area		PO Number	231753
Pipe Segment Reference	MH-1B - MH-1	Date	11/29/2023 14:27
Street	WALKERBILT RD	City	NAPLES
Comments			

Manhole

Upstream MH	1B	Rim to Invert (U)	
Grade to Invert (U)		Rim to Grade (U)	
Downstream MH	1	Rim to Invert (D)	
Grade to Invert (D)		Rim to Grade (D)	
Sewer Use	Sanitary	Direction of Survey	Downstream

Pipe

Height (Diameter)	6	Width	
Shape	Circular	Material	Polyvinyl Chloride
Lining Method		Pipe Joint Length	
Total Length		Length Surveyed	53.7
Year Laid		Year Renewed	

Misc

Flow Control	Not Controlled	Media Label	DVD
Purpose	Routine Assessment	Sewer Category	
Pre-Cleaning	Jetting	Date Cleaned	11/29/2023 13:26
Weather	Dry	Location Code	Main Highway - Suburban/Rural
Additional Info		Location Details	

Custom

Number of Taps	0	Number of Roots	0
Num Cracks / Fractures	0	Number of Broken / Holes / Collapse	1
Number of Deposits	0	Custom6	
Custom7		Struct Grade	
OM Grade		Overall Grade	

Pacp 6

Reverse Setup ID		Sheet (Group) Number	
Imperial Units (US)	True	Pressure Value	
Work Order		Project	RIVERBEND OF NAPLES SANITARY 11.29.2023
		Completed	Yes




Project: RIVERBEND OF NAPLES SANITARY




11.29.2023



Date: 11/29/2023 2:27:00 PM
Street: WALKERBILT RD
Length Surveyed: 53.7
Pacp Quick Overall Rating: 5141
Height (Diameter): 6
Street: WALKERBILT RD

Pipe Segment Reference: MH-1B - MH-1
Upstream MH: 1B
Downstream MH: 1
Direction of Survey: Downstream
Material: Polyvinyl Chloride

Distance	Fault Observation	Time	Picture
0.0	<p style="text-align: center;"> Manhole Severity: None Remarks: 1B </p>	37	
0.0	<p style="text-align: center;"> Water Level Severity: None Percent: 5 </p>	49	
0.0	<p style="text-align: center;"> Water Level Sag Severity: None Cont Defect: S01 Percent: 5 Struct Weight: 2 </p>	01:18	

Distance	Fault Observation	Time	Picture
3.1	<p>Material Change Severity: None Remarks: VCP</p>	03:21	 <p>MH 1B TO MH 1 RIVERBEND OF NAPLES SANITARY 11.29.2023</p> <p>11.29.2023 3.08 ft 636 mbar 794 mbar</p>
3.1	<p>Broken Position: 8 To 10 Severity: None Joint Struct Weight: 5</p>	04:09	 <p>MH 1B TO MH 1 RIVERBEND OF NAPLES SANITARY 11.29.2023</p> <p>11.29.2023 3.08 ft 635 mbar 792 mbar</p>
6.5	<p>Water Level Sag Severity: None Cont Defect: F01 Percent: 5 Struct Weight: 2</p>	04:48	 <p>MH 1B TO MH 1 RIVERBEND OF NAPLES SANITARY 11.29.2023</p> <p>11.29.2023 6.47 ft 635 mbar 792 mbar</p>

Distance	Fault Observation	Time	Picture
41.5	<p>Water Level Sag Severity: None Cont Defect: S02 Percent: 5 Struct Weight: 2</p>	06:48	
46.9	<p>Infil Runner Position: 6 To 11 Severity: None Joint Maint Weight: 4</p>	08:03	
50.5	<p>Water Level Sag Severity: None Cont Defect: F02 Percent: 5 Struct Weight: 2</p>	08:59	

Distance	Fault Observation	Time	Picture
50.7	<p align="center">Repair Localized Liner Severity: None Remarks: LINNER</p>	11:33	
53.7	<p align="center">Manhole Severity: None Remarks: 1</p>	12:41	


Project: RIVERBEND OF NAPLES SANITARY

11.29.2023

Date: 11/29/2023 2:27:00 PM
Street: WALKERBILT RD
Length Surveyed: 53.7
Pacp Quick Overall Rating: 5141
Height (Diameter): 6
Street: WALKERBILT RD

Pipe Segment Reference: MH-1B - MH-1
Upstream MH: 1B
Downstream MH: 1
Direction of Survey: Downstream
Material: Polyvinyl Chloride

Severity
Light
Moderate
Average
Heavy
Severe



Nassco C.C.T.V. Defect Code Information

Grade	Structural	O&M	Overall
5	5	0	5
4	0	4	4
3	0	0	0
2	6	0	6
1	0	0	0
Overall	11	4	15
Number of Defects	4	1	5
Pipe Rating	5123	4100	5141
Pipe Ratings Index	3	4	3

Nassco C.C.T.V. Defect Code Information

Distance	Video Ref	Code	Cont Defect	Value			Joint	Circumferential Location	
				Dimension		%		At / From	To
				1st	2nd				
0	37	AMH - Manhole							
		1B							
0	49	MWL - Water Level				5			
0	78	MWLS - Water Level Sag	S01			5			
3.1	201	MMC - Material Change							
		VCP							
3.1	249	B - Broken					X	8 10	
6.5	288	MWLS - Water Level Sag	F01			5			
41.5	408	MWLS - Water Level Sag	S02			5			
46.9	483	IR - Infil Runner					X	6 11	
50.5	539	MWLS - Water Level Sag	F02			5			
50.7	693	RPL - Repair Localized Liner							
		LINNER							
53.7	761	AMH - Manhole							
		1							

Videos Created for Session RIVERBEND OF NAPLES SANITARY 11.29.2023

1B-1_11292023-1429-D.mp4 Size: 289 MB

Your browser does not support the video tag.

Created with the  report generator

Project: RIVERBEND OF NAPLES SANITARY

11.29.2023

Date: 11/29/2023 2:27:00 PM

Street: WALKERBILT RD

Length Surveyed: 53.7

Pacp Quick Overall Rating: 5141

Height (Diameter): 6

Street: WALKERBILT RD

Pipe Segment Reference: MH-1B - MH-1

Upstream MH: 1B

Downstream MH: 1

Direction of Survey: Downstream

Material: Polyvinyl Chloride

Percent Grade Mean: -1.40

Plot Distance From: 0 To 55


Max Percent Difference: 3

Number of Window Values: 1

Percent Difference Max for Windows Values: 60

Number of Feet to Average: 1

Final number of points plotted: 44



Additional Reports for Session RIVERBEND OF NAPLES SANITARY 11.29.2023

Created with the  report generator

