

### Project Information

<b>Surveyor Name</b>	BUENO_R	<b>Certificate Number</b>	P0043820-082023
<b>Owner</b>		<b>Customer</b>	RIVERBEND OF NAPLES MOBILE HOA
<b>Drainage Area</b>		<b>PO Number</b>	231753
<b>Pipe Segment Reference</b>	MH-4 - C/O 4	<b>Date</b>	11/30/2023 17:24
<b>Street</b>	WALKERBILT RD	<b>City</b>	NAPLES
<b>Comments</b>			

### Manhole

<b>Upstream MH</b>	C/O-4	<b>Rim to Invert (U)</b>	
<b>Grade to Invert (U)</b>		<b>Rim to Grade (U)</b>	
<b>Downstream MH</b>	MH-4	<b>Rim to Invert (D)</b>	
<b>Grade to Invert (D)</b>		<b>Rim to Grade (D)</b>	
<b>Sewer Use</b>	Sanitary	<b>Direction of Survey</b>	Upstream

### Pipe

<b>Height (Diameter)</b>	6	<b>Width</b>	
<b>Shape</b>	Circular	<b>Material</b>	Polyvinyl Chloride
<b>Lining Method</b>		<b>Pipe Joint Length</b>	
<b>Total Length</b>		<b>Length Surveyed</b>	2
<b>Year Laid</b>		<b>Year Renewed</b>	

### Misc

<b>Flow Control</b>	Not Controlled	<b>Media Label</b>	DVD
<b>Purpose</b>	Routine Assessment	<b>Sewer Category</b>	
<b>Pre-Cleaning</b>	Jetting	<b>Date Cleaned</b>	11/30/2023 17:25
<b>Weather</b>	Dry	<b>Location Code</b>	Main Highway - Suburban/Rural
<b>Additional Info</b>		<b>Location Details</b>	

### Custom

<b>Number of Taps</b>	0	<b>Number of Roots</b>	0
<b>Num Cracks / Fractures</b>	0	<b>Number of Broken / Holes / Collapse</b>	0
<b>Number of Deposits</b>	0	<b>Custom6</b>	
<b>Custom7</b>		<b>Struct Grade</b>	
<b>OM Grade</b>		<b>Overall Grade</b>	

### Pacp 6




<b>Reverse Setup ID</b>		<b>Sheet (Group) Number</b>	
<b>Imperial Units (US)</b>	True	<b>Pressure Value</b>	
<b>Work Order</b>		<b>Project</b>	RIVERBEND OF NAPLES SANITARY 11.30.2023
		<b>Completed</b>	No

# Project: RIVERBEND OF NAPLES SANITARY

## 11.30.2023

Date: 11/30/2023 5:24:00 PM  
Street: WALKERBILT RD  
Length Surveyed: 2  
Pacp Quick Overall Rating: 4100  
Height (Diameter): 6  
Street: WALKERBILT RD

Pipe Segment Reference: MH-4 - C/O 4  
Upstream MH: C/O-4  
Downstream MH: MH-4  
Direction of Survey: Upstream  
Material: Polyvinyl Chloride

Distance	Fault Observation	Time	Picture
0.0	<b>Manhole</b> Severity: None Remarks: MH-4	24	
0.0	<b>Water Level</b> Severity: None Percent: 5	42	
2.0	<b>Camera Underwater</b> Severity: None Maint Weight: 4	01:12	

Distance	Fault Observation	Time	Picture
2.0	<p><b>Abandoned Survey</b>  <b>Severity: None</b>  <b>Remarks: POSSIBLE BREAK</b></p>	02:28	 <p>MH MH-4 TO MH C/O-4  RIVERBEND OF NAPLES SANITARY 11.30.2023</p> <p>11.30.2023  2.00 ft</p> <p>640 mbar  775 mbar</p>

Created with the  report generator


# Project: RIVERBEND OF NAPLES SANITARY

## 11.30.2023

**Date:** 11/30/2023 5:24:00 PM  
**Street:** WALKERBILT RD  
**Length Surveyed:** 2  
**Pacp Quick Overall Rating:** 4100  
**Height (Diameter):** 6  
**Street:** WALKERBILT RD

**Pipe Segment Reference:** MH-4 - C/O 4  
**Upstream MH:** C/O-4  
**Downstream MH:** MH-4  
**Direction of Survey:** Upstream  
**Material:** Polyvinyl Chloride

Severity
Light
Moderate
Average
Heavy
Severe



Created with the  report generator

# Nassco C.C.T.V. Defect Code Information

Grade	Structural	O&M	Overall
5	0	0	0
4	0	4	4
3	0	0	0
2	0	0	0
1	0	0	0
Overall	0	4	4
Number of Defects	0	1	1
Pipe Rating	0000	4100	4100
Pipe Ratings Index	0	4	4

# Nassco C.C.T.V. Defect Code Information

Distance	Video Ref	Code	Cont Defect	Value			Joint	Circumferential Location	
				Dimension		%		At / From	To
				1st	2nd				
0	24	AMH - Manhole							
		MH-4							
0	42	MWL - Water Level			5				
2	72	MCU - Camera Underwater							
2	148	MSA - Abandoned Survey							
		POSSIBLE BREAK							

Created with the  report generator

# Videos Created for Session RIVERBEND OF NAPLES SANITARY 11.30.2023

MH-4-CO-4\_11302023-1725-U.mp4 Size: 58.8 MB

Your browser does not support the video tag.

Created with the  report generator

# Project: RIVERBEND OF NAPLES SANITARY

11.30.2023

**Date:** 11/30/2023 5:24:00 PM

**Street:** WALKERBILT RD

**Length Surveyed:** 2

**Pacp Quick Overall Rating:** 4100

**Height (Diameter):** 6

**Street:** WALKERBILT RD

**Pipe Segment Reference:** MH-4 - C/O 4

**Upstream MH:** C/O-4

**Downstream MH:** MH-4

**Direction of Survey:** Upstream

**Material:** Polyvinyl Chloride

Percent Grade Mean: -22.90

Plot Distance From: 0 To 3

Max Percent Difference: 3

Number of Window Values: 1

Percent Difference Max for Windows Values: 60

Number of Feet to Average: 1

Final number of points plotted: 1

Created with the  report generator



# Additional Reports for Session RIVERBEND OF NAPLES SANITARY 11.30.2023

Created with the  report generator

